Newer model Chrysler vehicles equipped with CAN and a Harman/Becker RB3 radio which are experiencing a battery drain issue should check related components on the CAN bus causing the radio to remain on. Philips has reported a CAN chip, that when defective, causes the CAN bus to show bus activity resulting in the radio remaining on and subsequently draining the battery. Before replacing the RB3 radio, check the vehicle's CAN bus for a module remaining on. This can cause the RB3 radio to seem defective when in fact there is nothing wrong with the radio.